

The throttle vacuum positioner assembly located on the base (choke housing side) has not been installed on this carburetor.

Part # D5TZ9S5553-B has been discontinued by the manufacture. Although the carburetor will function without this assembly, we recommend installing this part from the original carburetor.