

PART #:C816, C816A, C817, C823, C839, C839A, C841, C841A, C847, C847A & C896

Due to parts availability it may be necessary to install the choke cable bracket from the carburetor being replaced, on the remanufactured unit.