


ST Blade Fuse Block

3 Independent Sourced Circuits, 3 Common Sourced Circuits
PN 5035 / PN 5037

Wiring Diagram Example

3 24-Hour Circuits, 3 Switched Circuits



Push yellow latch
down to open
the cover

