

The base mounting gasket is not supplied by the manufacturer. You must re-use the old one to mount this carburetor.